


IMPORTANT SAFETY RECALL

Porter-Cable and DeVilbiss Power Co. Air Compressors

The air compressor motor can overheat, posing a fire hazard.

The following models with manufacture dates after 02-11-08 or 2008-07-xx are potentially affected:

Porter-Cable: C3101-2, C3151-2, C6110-1, C6110-2
EXCELL: EXFBC6025-1
Pro-Air II PAFBC6025VP-1



Mod. ABC00000000-00

HP	Gal	Displacement Displacement / Absorption
00	0	00.0 CFM
Electr.	120V/240V/15A/8A/60HZ/1PH	Air Delivery (SCFM) Discharge Airflow (SCFM) Output (SCFM)
Pump / Compressor	Max. PSI / Bar / Max.	0.0 SCFM @ 40PSI 0.0 SCFM @ 90PSI
AC-0000	000 PSI	0000
CL-0000		
CALIFORNIA CODE 482 (1) (2)	COMPLIES TO STANDARD NO. 14CA 100	SER. NO. 9999999999 WG
DeVilbiss Air Power Company Jackson, TN 38301-9615 1-800-888-2468		COVERED BY U.S. PATENTS 4,871,688 PATENTS PENDING

99-99-99

Manufacture Date
MM-DD-YY
or
Year (4 digits)-Week (2 digits)-xx

The model number and manufacture date can be found on the nameplate of the compressor, located on the tank.

CHECK your motor end cap for an affected motor as shown below



Closed Air Slots



Open Air Slots



No Air Slots



If your compressor is affected, UNPLUG AND STOP USING IT IMMEDIATELY, and call toll free

1-866-885-1877

between 8 a.m. and 6 p.m., Eastern Time, Monday through Friday.