

IMPORTANT SAFETY RECALL

PORTER-CABLE® 890 Series Routers

It may be possible, under certain circumstances, for the motor insulation to be abraded, creating a potential shock hazard.

PRODUCTS AFFECTED:


| Model Number | Description | Affected Serial Number Range |
|--------------|--|------------------------------|
| 891 | 2-1/4 PEAK HP GRIPVAC™ ROUTER | 10001 through 24647 |
| 892 | 2-1/4 PEAK HP ROUTER KIT | 10001 through 68442 |
| 893PK | 2-1/4 PEAK HP MULTIBASE ROUTER KIT | 10001 through 68442 |
| 894PK | 2-1/4 PEAK HP MULTIBASE ROUTER KIT WITH GRIPVAC™ ATTACHMENT | 10001 through 24647 |
| 895PK | 2-1/4 PEAK HP MULTIBASE ROUTER KIT WITH ROUTER TABLE HEIGHT ADJUSTER | 10001 through 68442 |
| 8902 | 2-1/4 PEAK HP VARIABLE-SPEED MOTOR | 10001 through 68442 |

Units with an “T” stamped on the name plate are not affected.



Model Number

Serial Number



If your router is affected, STOP USING IT IMMEDIATELY, and call PORTER-CABLE® toll-free at

1-800-949-6348

between 8:00 a.m. and 6:00 p.m. Central Time, Monday through Friday, or visit www.porter-cable.com for the location of a service center to obtain a free inspection and repair, if necessary.

PCB-0705